

ILMAILULAITOS
CIVIL AVIATION ADMINISTRATION

PL 50
FIN - 01531 VANTAA, FINLAND
Puhelin/Telephone 09 - 82 771
International + 358 9 82 771
Telefax 09 - 82 772499

LENTOTURVALLISUUSHALLINTO
FLIGHT SAFETY AUTHORITY

LENTOKELPOISUUSMÄÄRÄYS
AIRWORTHINESS DIRECTIVE



M 637/75

28.10.1975

The modification described in this Airworthiness Directive is necessary for the continuous airworthiness of the aircraft, The work performed is to be files in the Journey Log Book.

PIK-20. Wearing of the rudder operating cable

Applicability: PIK-20 sailplanes with serial numbers 20004 to 20058

Reference: Molino Oy Service Bulletin no. M6.

Accomplishment: At the next monthly or annual inspection after 1st November 1976.

Action:

1. Inspect in accordance with the referenced Service Bulletin whether the geared rod has been rubbing against the rudder cable cover. If the cover tube has been badly worn replace the damaged area and if the cable has been damaged replace it.
2. Bond the cover tube to the fuselage outer skin in accordance with the referenced Service Bulletin.